

UN1CO



1L

VOC-FREE

Ciranova® products are made for the professional user. The instructions specified in the data sheet are formulated after necessary tests were performed and after years of experience. However, they are drawn to our best knowledge and ability. The user must test the application of the product in the for him applicable conditions. Guarantee can not be derived out the text of this technical description.

PRODUCED BY DEBAL COATINGS NV

Industrieweg 29 – B 8800 Beveren-Roeselare
tel +32 (0) 51 30 11 40 fax +32 (0) 51 31 26 48
www.ciranova.be ciranova@ciranova.be

PRODUCT DESCRIPTION

UN1CO is a 1-coat oil from the newest generation using renewable natural oils. Thanks to its special technology there is only one coat needed to finish your parquet. The combination of the oil with the hardener results in a fast drying and excellent chemical and mechanical resistant finish.

TECHNICAL DATA

VISCOSITY +/- 40 SEC (DIN 4MM)

SOLID CONTENT 100% BY WEIGHT

DENSITY +/- 0,95 KG/L

COBALT FREE

VOC-FREE

PREPARATION

Sand the surface with grain 120 – 150 and remove afterwards the sanding dust.

USER TIPS

Mix the oil with the hardener (100/30) and let the product rest for about 10 minutes. Dilute a small quantity with a cloth or polishing machine and let the product dry for a few minutes. Remove the superfluous oil within 15 minutes with a cloth or polishing machine. Check afterwards if the surface feels handdry.



DRYING TIMES

Slightly walkable after 24 hours drying depending on the type of wood, the temperature, the humidity.



APPLYING QUANTITY

+/- 40 - 60 m²/liter per coat

AFTER TREATMENT

Clean regularly with flooring soap Ciranova. Depending on the frequent use of the parquet, use maintenance oil periodically and for thorough cleaning, use Intensive Cleaner Ciranova.

ATTENTION : UN1CO needs +/- 2 weeks to fully cure. Don't use any water or maintenance products on the floor during this period.

PRODUCT INFORMATION

Shelf life : 1 year in original and well closed original packaging.

Potlife : +/- 3 hours.

Storage frostfree.

SPECIAL QUALITIES

Dried and used cloths or pads should be plunged in water because of the danger for spontaneous combustion.